



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE BULLETIN

NO.: 2083 Rev A

TO: All Garmin Aviation Service Centers
DATE: July 15, 2020
SUBJECT: GNS 4XXW and GNS 5XXW GPS Date

PRODUCTS AFFECTED

GPS 400W, GNC 420W/AW, GNS 430W/AW, GPS 500W, and GNS 530W/530AW/TAWS products are affected.

PURPOSE

Beginning August 16, 2020, the GNS 4XXW and GNS 5XXW may report an incorrect GPS date in either of the following situations:

- the GPS receiver has not acquired a 3D navigation solution within the last 128 weeks
- a unit Master Reset (holding the CLR button while energizing the unit) is performed

An incorrect GPS date may result in the following:

- All installed databases with effective dates will show as not yet effective
- Weather datalinks (Sirius/XM, FIS-B, and Connex) will not display weather

© 2020

Garmin Ltd. or its subsidiaries

All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.